

# APPENDIX - RAIL CAR 360

## CURRENT CONDITIONS



- Vertical members of the frame are called stiles while the horizontal members are known as rails.
- Over time the absorption of water has caused rot and paint degradation.
- All windows should be checked



# WINDOW STILES AND RAILS (MORE EXAMPLES)



# VANDALISM





# VARIOUS AREAS NEED TO BE REPAINTED



# **PAINTING NEEDS AT CAR ENTRANCE**





# SIGNAGE RESTORATION



# HARDWARE RESTORATION - TOILET SEAT



# INTERIOR WOOD THROUGHOUT CAR 360



- General repair and finish care

